

All COR ISO Recommendations

Latent Condition, Seismic and ISS

Friday, October 12, 2012 12:54:48 PM

Type	Rec #	ABU	Unit	Year (I/R)	LC or ISS Question #	LC Question ISS Question Seismic Area	Observation	Recommendation	Resolution	Duc Date	Assigned To	Status
Seismic	633	U&E	TG-800	2010		T-850	Anchor bolts at west end of tank do not have nuts. (Pics 1, 2, &3).	Install nuts on anchor bolts.	Anchor bolt nuts have been installed.	10/5/2011	Reyes, Donald S.	Completed
Seismic	634	U&E	TG-800	2010		Pipe support for oil return pipe south of TGA800	Anchor bolts for pipe support do not have nuts (Pics 4 & 5).	Install nuts on anchor bolts.	lkdjflsdckfjsdk	10/5/2011	Reyes, Donald S.	Completed